## Thermostat, 20 - 110 °C

P/N: 014001201





Similar to illustration, technical modifications reserved. Without decoration.

## **Technical data**

Weight: 0.1 kg

The thermostat 20 - 110 °C is used for precise temperature control and the efficient storage of temperature sensitive products. The thermostat 20 - 110 °C allows for easy integration into existing systems, thereby supporting the smooth transport and organisation of goods.

Time and date of the request: 05.02.2025, 22:51:30

All information / dimensions are approximate, technical changes reserved. © Hupfer